Message

From: Moore, Gary [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=D9494EB3B37241B09CE3BDEAFF4C557A-MOORE, GARY)

Sent: 11/21/2018 1:30:35 AM

To: Don Edgington [d.edgington@erllc.com]

Subject: Re: DWO(s)

Don

The truck loads do not match up for the non-TSCA Soils. It shows 12 and 12 with total to date as 25

Sent from my iPhone

On Nov 20, 2018, at 5:51 PM, Don Edgington < d.edgington@erilc.com > wrote:

Good evening, everyone.

Attached please find a revised DWO for 11/19/18 and one for today's activities. Please note the DWO for today will cover demobilization for the break and any off-site removal activities that may be required until our return to the site.

The utility strike was repaired within the hour, flow tested for leaks and the repair passed with no issues. Comparable ¾" PVC was used for the repair.

If you have any questions or comments, please advise.

Have an enjoyable Thanksgiving with your families and friends.

Regards,

Don

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.

```
<DWO No. 14 - F.J. Doyle Salvage Site - 11.19.18.pdf>
```

<DWO No. 15 - F.J. Doyle Salvage Site - 11.20.18.pdf>